AMENDMENTS TO THE DRAWINGS

The drawings were objected to because it was unclear from Figure 3 where the housing ends and the pin begins particularly around feature 2. Applicants have amended Figure 3 to clarify where the housing ends and the pin begins around feature 2. Accordingly, Applicant submits herewith a replacement drawing sheet for Figure 3.

10/014,384 -12-



REPLACEMENT

Title: TAMPER RESISTANT PIN CONNECTION Inventor(s): Christopher J. Conway et al. Serial No. 10/014,384 - Filed November 9, 2001 Atty. Ref.: 9858-000037

1/1




FIGURE 3